

# CAUTION

Dispensing liquid nitrogen requires:



proper  
cryogenic  
gloves

goggles &  
face shield



+



lab coat  
long pants  
closed-toe shoes

*Purchase proper PPE through the Science Storeroom, 577-3098*

WSU Office of Environmental Health & Safety

[www.oehs.wayne.edu](http://www.oehs.wayne.edu)

577-1200

